




Board Meeting: January 21, 2019



Bond 2017 Update

Middle School South Auditorium

Final Completion February 15, 2019


Early Childhood Center

Construction in Progress

Substantial Completion July 2019



High School Historical Arch



North Side Sidewalk & Accessible Curb Ramp

South Side Sidewalk & Accessible Curb Ramp

Bond 2017 – Middle School South Auditorium



MSS – Main Entrance Canopy

Bond 2017 – Middle School South Auditorium



MSS – Main Entrance Canopy



Bond 2017 – Middle School South Auditorium



MSS – Main Entrance Canopy





Bond 2017 – Middle School South Auditorium



MSS – Main Entrance Lobby




Bond 2017 – Middle School South Auditorium



MSS – Main Entrance Lobby

Bond 2017 – Middle School South Auditorium





MSS – Stage Platform



Bond 2017 – Middle School South Auditorium



MSS – Stage Platform

Bond 2017 – Middle School South



MSS Proposed Front Entry Canopy Sign




Bond 2017 - Early Childhood Center



Early Childhood Center Front Entry Rendering



Bond 2017 - Early Childhood Center



Early Childhood Center Area Designations



Bond 2017 - Early Childhood Center



PRK Pavement - LOC Entrance, Bus Loop, Parent Drop-Off & Stacking Drive

Bond 2017 - Early Childhood Center



A

Classrooms

D

Classrooms

G

Classrooms

Parent Drop-Off
Staff Parking

H

Cafeteria-Kitchen-Activity

E

Library-LGI-Computer

B

Administration

J

Classrooms

F

Classrooms

Bus-Loop & Parking

C

Classrooms



Early Childhood Center Area Designations



Bond 2017 - Early Childhood Center



Area A Classroom Slab Complete



Bond 2017 - Early Childhood Center



Area D & G Classroom Exterior Framing & Roof Decks Complete



The ECC project abbreviated list of the steps taken in effort to expedite the recovery schedule.

1. Rented crane mats for site access to aid work in wet conditions.
2. Increased concrete, metal framing, and steel erection crews and manpower in each crew
3. Crews are working longer hours daily, working evenings, weekends, and holidays:
Worked Christmas Eve
Workforce averaged 60 people on site on the week of Christmas
Working most Sundays as well. 15 people on site this past Sunday (1/13/19) working on sunshade steel.
4. Coordinating with subcontractors to isolate ways in which the schedule can be reduced.
5. Electrical variance requests for conduit installation and MC cable in walls
6. Continue to supply and blend countless pallets of dry lime to wet soil to:
Have the ability to pass trench backfill testing
Subgrade preparation in effort to expedite placement of concrete slabs on grade to dry access roads.

Bond 2017 - Early Childhood Center



ECC Parent Drop-Off – Service Court



Bond 2017 - Early Childhood Center



ECC Parent Drop-Off – Service Court



Bond 2017 - Early Childhood Center



ECC Service Court Grease Trap





ECC Area G Classroom Structure

Bond 2017 - Early Childhood Center



ECC Area G - Classroom Infill – Piers & Grade Beams




Bond 2017 - Early Childhood Center



Steel Erection, Duct Hangers, Power Conduit




Bond 2017 - Early Childhood Center



Area B & E Steel Erection, Duct Hangers, Power Conduit




Bond 2017 - Early Childhood Center



Area E Steel Erection, Duct Hangers, Power Conduit

Bond 2017 - Early Childhood Center



Main Power Service Underground




Bond 2017 - Early Childhood Center



Area H & E Steel Erection, Duct Hangers, Power Conduit



Bond 2017 - Early Childhood Center



Area G Plumbing Risers





Thank You